



## Lloyd's Register of Shipping,

201, Tower Building,

Liverpool, 3, 19th October, 1948.

RECEIVED

20 OCT 1948

Reference

Dear Sir,

In reply to your letter of the 14th instant, regarding the Liverpool F.E. Report No. 127547 on the "TOMOCYCLUS", I have to acquaint you I am informed by the Surveyors that the ship's service air receiver was not examined and perhaps you will kindly add this to the items remaining to complete the survey.

Your remarks regarding the test of the steam pipes are noted.

Yours faithfully,

Secretary to the  
Liverpool Committee.

The Secretary,

LONDON.



© 2020

Lloyd's Register  
Foundation

002858-002869-0353



Referred to the D.O.

*RJ*

For Engineer Surveyors (F.E. Rpts.) to note

Noted. See endorsement of 13/10/48.

*Swk. 25/10/48*



© 2020

Lloyd's Register  
Foundation