

27 NOV 1959

ME "ISLANDER" REPORT Sng. No. 13541

ing Conditions of Class: NONE.

ACTION is DEFERRED for examination in dry dock after grounding.

pendix. (~~as before~~ None)Present Survey: (~~as before~~ in dry dock)

Docking: Damage (grounding) involving bottom shell plating etc. in way fore peak and Nos. 1 & 2 D.B.tanks (p & s)

ation:

SUBMITTED record of 'DS 10,59' be assigned subject to indented bottom shell plating etc. in way fore peak tank and Nos. 1 & 2 D.B.tanks (p & s) being specially examined and dealt with as necessary next drydocking.

DS 10,59 Subject

~~DELETE FROM S.R.L.
Drydocking(grounding).~~

IT IS FURTHER SUBMITTED the Surveyors be advised the class is subject to the above and be requested to issue an amended Interim Certificate.

Lloyd's Register
Foundation

002876-002882-065