

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *Steel S.S. "PENTEIFI"*

Rpt.

*hon  
Mdb*

No. *83697  
10896*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Key *First Entry*

Before this Case receives consideration the Middlesbrough Surveyors should be requested to state whether Side Stringers are fitted as shown on the plans; if they are correct in stating the bulkhead on line N<sup>o</sup> 70 and the Collision bulkhead extend to the Awaiting and other decks respectively; whether the bottom shell plating thicknesses have been verified as far as practicable and whether the 8" dia rivets the shell plating butts are spaced  $3\frac{1}{2}$ " or  $3\frac{1}{2}$  dia apart.

*5/1/21*



© 2020

*MR*  
*5-1-21*  
Lloyd's Register  
Foundation

002883-002890-0053