

ass is subject to

4E

- (1) Starboard Main Engine No. 4 crankpin (imposed 6.57)
being examined and crack detected by 9.62.
(2) Starboard stern bush (bronze) being renewed by 5.62.

11 MAY 1962

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....


VESSEL'S NAME....."INDIA".....REPORT.....HAM.....No. 11485.

Docking.

The Surveyor reports some damage repairs effected to the propeller.

IT IS SUBMITTED that this vessel is eligible to remain as classed, subject as above.

[Handwritten signature]



© 2000

Lloyd's Register
Foundation

002883-002890-0243