

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

22nd February 1962.

Dear Sirs,

S.S. "TURKISTAN"

R
With reference to the Boiler Survey, which became due at the end of November last, all safety valves require to be adjusted to complete this inspection.

In reply to enquiry, the Owners' London representatives state that they understand that this matter has been dealt with at your port. In the circumstances, I shall be glad if you will forward a copy of their Surveyors' report to this office should the matter have been dealt with as stated.

Any fees and expenses in connection with the survey should be collected from the Owners' local agents.

Yours faithfully,

Clerk to the
Classification Committee.

Messrs. Fraser & Shepherd Ltd.,
Lloyd's Agents,
25 Industry Road,
(P.O. Box 525),
PORT HARCOURT,
Southern Nigeria.



© 2020

Lloyd's Register
Foundation

002897-002906-0207