

Chief Engineer Surveyor _____ Received from Chief Engineer Surveyor _____
NAME Cardium Rpt. Nwe. No. 87874

As of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

of Engine oil requires 450 SA.

If Boilers fitted with forced draught ✓
Tail Shaft. If fitted with a continuous liner Yes
If fitted with an outside gland of } no
approved type

This vessel's machinery appears to have been built in accordance
the Rules and the approved plans, and it is submitted she is
ble to be classed Full @ 12-27

2019 150th

20/10/2021



© 2021
Lloyd's Register
Foundation

007407-007915-0061