

Chief Ship Surveyor .....

Received from Chief Ship Surveyor ..... 15 OCT 1959

NAME "COLUMBIA" ..... REPORT Pir. No. 8151

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

The Notation "Laid Up - Surveys Overdue" appears in the Register Book.

Prior to the ship being laid up the class was subject to chain locker being specially examined at the next drydocking.

There was also an S.R.L. Appendix Note.

The PIRAEUS Surveyors report (8,59), ship examined in dry dock and the requirements of a General Examination carried out to enable her to proceed under own power to Japan as an unclassed ship. (Refer letter dated 30,7.59).

The Surveyors further report shell plate A.2 etc. (p.s.f) specially examined on account of heavy weather and ice damage.

In view of the above IT IS SUBMITTED ACTION be DEFERRED pending further information.

IN S.R.L. APPENDIX.  
Indents in sheerstrake and side shell plating (p.s.).

*OK*  
5-10-59



© 2021

Lloyd's Register  
Foundation

002907-002915-0117