

THROUGH GLASGOW

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex  
Telex No.: 24305

Telephone: ROYal 9166

25th November, 1959.

(S)

Dear Sirs,

Steamer "CAPTAIN COOK"

A report of a survey held at Wellington on the 4th and 5th November has now been received from the Society's Surveyors, from which it is noted that some temporary repairs were carried out to the port side of the main injection four-way branch piece.

It was recommended that this branch piece should be renewed on the ship's return to the United Kingdom and that the starboard propeller should be specially examined and dealt with as necessary at the next drydocking. The Committee have continued the class subject, inter alia, to these matters receiving attention.

I shall be obliged if you will let me know at which port the branch piece will be renewed in order that the Society's Surveyors may be informed.

Yours faithfully,

C.C. GLS.

Deputy Clerk to the  
Classification Committee.

Messrs. Donaldson Brothers & Black, Ltd.,  
14, St. Vincent Place,  
GLASGOW, C.A.

© 2021  
BS due 6.59  
Lloyd's Register  
Foundation

002929-002937-0172