

Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

1261 NVP 38  
JAN 1932

NAME Steel Sc. "RUKAMAVATI"

Report Kch.

No. 477

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/1923.)

vey \_\_\_\_\_ When due \_\_\_\_\_

The class is subject to damage through collision being repaired at the Owner's convenience.

The S.S. No.1 became due 2.30 and enquiries have been made from time to time.

The Bombay Surveyor now forwards letters from the State Mechanical Engineer stating that it is not intended to carry out the S.S. No.1.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owner's request.

Withdraw Class.

Port ...



© 2020

Lloyd's Register  
Foundation

002938-002446-0187

21.1.31.