

Ceiling in Holds, thickness and material *none*
Steel plates welded to deck except in hold.

Cargo Batches, thickness, ma

Hatche

5

Req. 1.

(Received at London Office,.....)

18 SEP 1947

No. 5849 Port

NEWCASTLE-ON-TYNE

Date 12th September 1947

We hereby request that the Single Screw Motor Oil Tanker Building
for The British Tanker Co. Ltd. by Swan, Hunter & Wigham Richardson Ltd.

of 8,580 Gross Tons. Length, P.P. 463' - 5 1/2" breadth, mld. 61' - 9" depth, mld. 34' - 1"

may be Specially Surveyed while building (Lloyds + 100A1 Carrying Petroleum in) If for a particular term
(bulk with longitudinal framing at bottom & at deck) or class, state the same.

We hereby engage to pay the established Special Survey Fees as set forth in the Society's Rules, or
any variation therefrom which has been duly notified and, in addition, any travelling and other expenses
which may be incurred by the Surveyors in connection with the survey.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping,
which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be
held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register
Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member
thereof, or the Surveyors, or other Officers or Agents of the Society."

No. 1866 in Builder's Yard.

Manufacturers of Engines Swan, Hunter & Wigham Richardson, Ltd.

Ditto

of

Boilers Swan, Hunter & Wigham Richardson Ltd.

Signature

SWAN, HUNTER, & WIGHAM RICHARDSON, LTD.

To the Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—
"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

00438-00946-0286