

Received from Chief Ship Surveyor

8 SEP 1959

SHIP'S NAME "THELICONUS" REPORT Rot. No. 7832

GB

Outstanding Conditions of Class: SUBJECT to pitted shell plating (p & s amids) being examined at successive drydockings and to lower portion of sternframe and butt (T.W.10,58) being specially examined next drydocking.

R.L. Appendix. (As before ~~xxx None~~)

Structure of Present Survey: (~~At sea~~ and in dry dock)


Docking: Repairs.

Recommendation:

SUBMITTED record of DS 8,59' be assigned as recommended, subject as above, and to top pintle of rudder, air pipes to cofferdam (s.s.a) and cross bunker (p.s.a) being specially examined and dealt with before ship is re-commissioned, and to set in shell plates H.7, J.7 & 14, K.17 & 18 (p.s.) and J.12, and K.12 (s.s.), all from fwd, being specially examined and dealt with as found necessary by the Special Survey.

DS 8,59 Subject  
IN S.R.L. APPENDIX.  
Sideshell plating (p & s) indented.

Blk (new)



© 2025

*Jan. 3/9/59*

C.S.S. Records Dept.  
to note.



Lloyd's Register Foundation

002956-002969-0353