



RECEIVED

- 3 APR 1950

ANSD

# Lloyd's Register of Shipping,

95, Bothwell Street, GLASGOW, C.2.

31st March, 1950.

S. Dear Sir,  
(D.O.)

## Motor Tanker "BRITISH COMMANDER"

In reply to your letter of the 29th instant regarding Glasgow First Entry Report No. 75168, the Surveyor states that both the thickness of the side girders in the double bottom tank and the bridge side plating at after end should have been shewn as .60 on his report and he regrets the error.

Yours faithfully,

Secretary to the  
Scottish Committee.

The Secretary,  
LONDON.



© 2020

Lloyd's Register  
Foundation

002978-002988-0108

002978-002988-0110

Referred to the D.O.

For Ship Surveyors (F. E. Rpts.) to note.

5/10/20  
5-4-50



© 2020

Lloyd's Register  
Foundation