

VILHELM NIELSEN
THORSHAVN

To Lloyd's Register of Shipping, London.

Dear Sirs,

Regarding steamtrawler "Kallsevni" of Thorshavn

On request of the owner I have during the days the 7th and 8th of **July** 1948 inspected the Feed Pipe, the Feed Valve and the Bottom Blow-off Valve.

A new Check Valve was made. The Feed Pipe was after welding tested to twice the boiler pressure and found to be tight.

The Bottom Blow-off Valve was badly coroded. As a temporary repair the seating was welded and a new valve was made. After this the valve was tested to twice the boiler pressure and found to be tight.

It is recommended that a new Valvehousing being mounted before the trawler is going out fishing again.

Thorshavn July the 9th 1948

Vilhelm Nielsen



© 2020

Lloyd's Register
Foundation

002978-002988-0190