

24 JAN 1963

Ship's name: CLAN MURRAY

Port Manila (9 B) No. 4541

Ship is subject to Port boiler inboard wing frame Last survey date 2/11/62
being renewed by 1/62 (2 months limit).

M.B.S. (due 2/62) commenced 6/62, NOT advanced.

Repairs


Boiler feed check - valves of starboard and centre
boiler repaired. Forward main feed pump water end cover repaired.
The Surveyor makes no recommendation and it is not recommended
that the forward feed pump water end cover be renewed by
2/63. (3 months limit).

C.S. Advanced.

It is submitted that this
vessel is eligible to remain
as **CLASSED**, subject as above and as recommended.

To complete the M.B.S.

Port boiler to be examined
and its 8 1/2" adjusted valves
subject etc to be dealt with.



© 2020

Lloyd's Register
Foundation

24/1/63.

00947-003005-0157