

COPY

# LLOYD'S REGISTER OF SHIPPING



Port HONG KONG.

8th October, 1962.

This is to Certify that I have surveyed part of the machinery  
of the S.S. "CRONULLA", 2330 Gross tons, of Hong Kong,  
for Main Boiler Survey and Part Engine Special Survey, whilst  
the vessel was lying afloat at this Port,

and that all my recommendations have been carried out to my satisfaction. I  
am reporting accordingly and recommending to the Committee of Lloyd's Register  
of Shipping that the machinery classification should be retained and the following  
survey records assigned M.B.S. 8,62, and E.S. (with date), when  
the respective surveys have been completed.

Parts now examined:— For E.S.

Main Engine

M.P. cylinder, cover, piston and rod.  
All valves and gear.

Outboard feed pump.  
Main Circulating pump.  
Main Condenser.

To Complete the Main Boiler Survey :—

All safety valves remain to be adjusted under steam,  
oil fuel burning and remote controls to be examined under  
working conditions.



(Signed) D.C. Wood.

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey  
CSM Continuous Survey of Machinery  
DBS Donkey Boiler Survey  
ES Engine Special Survey

MBS Main Boiler Survey  
OF Fitted for oil-fuel (date) FP above 150° F.  
SGS Steam Generator Survey  
SPS Steampipe Survey

TS Tailshaft Survey  
TS(CL) Tailshaft Survey—Continuous Liner  
TSN Tailshaft renewed  
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."