

TELEPHONE: SUNDERLAND 4093 (2 LINES).

## Lloyd's Register of Shipping,

ENCLOSURE.

55, Fawcett Street,

Sunderland, 6th December, 1948.

Reference  
"S"

Dear Sir,

RECEIVED  
- 7 DEC 1948

s.s. "ADMIRAL FRASER".  
Sunderland F.E. Report No. 34997.

In reply to your classing letter of the 3rd instant, we have to confirm that the machinery spare gear complies with the Rule requirements.

The diesel engine driving the generator was manufactured by Messrs. J. & H. McLaren Ltd. The engine number taken from the ship is 21168. In response to several enquiries of the Leeds Surveyors, we think it well to enclose a copy of their letter dated the 16th November. We have no knowledge of engine No. 30610.

Two ordinary type safety valves, each  $2\frac{3}{4}$ " dia., are fitted to each boiler, as in the case of the "NEPERTIT".

The omissions are regretted.

Yours faithfully,

THE SURVEYORS,  
PER:

*J. Grieve*

The Secretary,  
LONDON.



© 2020

Lloyd's Register  
Foundation

003018-003022-0083




23. 1891

卷之四

Lloyd's Register  
Foundation

For Engineer Surveyors (F.E. Reps.) to note.  
Noted Enk 9/12/48



For Engineer's  
Noted Enk

9/12/88

Length.

### Water Capacity.

Where Fitted.

Length.

### Water Capacity.

Feet.  
96.75

Tons.  
42.

Fore peak tank,

Feet.  
21.0

91.6 Tons