

9-AUG 1954

Rpt. C. 11 (Contd.)

Index No. ....

## LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Ship's Name "CANBERRA" of "Admiral Fraser" Official No. 182879.

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in

Alterations:-

A 24" dia x 1.10" thick Samson Post ventilator fitted (ps) in way of bridge front.  
Upper + tween deck plating efficiently doubled + ports stayed to bridge front.

<sup>std.</sup>  
Tween deck erected between Nos 4/5 tween decks, tonnage openings fitted.  
openings 4'6" x 3'0". - portable plate with hook bolts.

Deckhouse amidships entrance rearranged.

Additional door fitted (ps) opening 5'0" x 23". 24" coaming. 2" wood door. <sup>operated both</sup> sides.

Wood door (ss) at forward end repositioned outboard.

Existing W.T. door (ss) repositioned 6'0" aft. opening 5'0" x 2'6".

New access opening to tween deck stores (ss). opening 3'6" x 3'0".

" " " " " (ps). " 4'9" x 27"

Deck plating in way of openings efficiently doubled.

Original access opening to tween deck stores (ss) plated over.

To Plans Room  
Have you any  
comments to  
make about  
Derrick post?

James Fleming  
Glasgow  
7/8/54.

Noted  
FR.  
9.8.54

No  
10.8.54



© 2020

Lloyd's Register  
Foundation