

4E

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor..... 12 AUG 1957

NAME..... THORNBURY

REPORT.....

Hfs

5941

Ams

No. 21487

MBS due 4.57, partly held 4.57, now completed

Repairs. *The Helmsman Surveyor reports 2 cc stays broken & recommends  
2 stays in the starboard compartment chamber of the starboard locker  
to be renewed as soon as possible*

IT IS SUBMITTED this vessel is eligible for  
the record ~~BBS 6.57.~~

*MBS 4.57 subject as recommended*



*CDM*  
7.8.57.



© 2021

Lloyd's Register  
Foundation

003023-003028-0017