

GAE.

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 9166

17th February, 1958

Dear Sir,

S.S. "THORNBURY"

With reference to your report No. 59~~8~~¹ the safety valves were adjusted by the Amsterdam Surveyors on the 4th June last, and the ship was assigned the record MBS 4,57 subject to two stays in the starboard combustion chamber of the starboard boiler being renewed as soon as possible. I shall be glad to learn whether any further information is yet available regarding this item. A further complete Main Boiler Survey will become due at the end of April next.

The ship will become due for Screwshaft Survey at the end of April, and the Owners' intentions regarding the carrying out of this inspection will also be appreciated.

Yours faithfully,

Clerk to the
Classification Committee.

A. Weber, Esq.,
HELSINGFORS.

c.c. Stockholm



© 2021

Lloyd's Register
Foundation

003023-003028-0018