

Lt. Pluie Koppen

Ln 233

Before dealing with this case, it is submitted that  
the Surveyor be requested to state if the screw shaft  
is covered with a brass liner for the whole length of  
the stem tube; he should also be requested to state  
if he is certain that the diameter of the propeller is 15' 5"

Em. S.

25-4-05

Lt. S.

25-4-05

© 2021

Lloyd's Register  
Foundation

003023-003028-0033