


COPY

LLOYD'S REGISTER OF SHIPPING



Port L O N D O N

17th June, 1960.

This is to Certify *that I have*

Surveyed the Machinery of the S.S. "INVENTOR" 6261 tons gross of Liverpool, whilst afloat and subsequently in drydock in this port for a General Examination for deferment of Special Survey

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also

that I will Recommend that in the case of this Vessel the following
Survey Records be ~~made~~ retained in the Supplement to the Register Book
without fresh record of survey

and that her Machinery Classification Record be continued in the Book.

subject to the main overboard discharge chest again being specially examined and dealt with as found necessary and the high main injection chest being renewed before the end of June, 1961 and to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:

(C.S. Items only)

PARTS NOW EXAMINED FOR DEFERMENT OF SPECIAL SURVEY

Main engine H.P. cylinder, cover, piston and rod, connecting rod, crosshead pins and bearings guides and shoes and crankpin and bearing

Sea connections comprising:- high and low main injections, ballast injection, main overboard discharge and blowdown cocks (two Main and auxiliary machinery under working conditions. Electrical Installation megger tested.

Engineer Surveyor to Lloyd's Register

T.E. DRAGGETT.

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)

003023-003028-0072

© 2021

Lloyd's Register
Foundation