

31st January, 1961.

DUBLIN

9065, 72 - As recommended.

"CAPE DREPANON" Before your report No. 9070 receives the consideration of the Committee. I shall be glad to learn whether the boiler oil fuel heaters (two), the feed water heaters and the fire extinguishing arrangements were examined as it would appear from your report that these items are still outstanding to complete the Engine Survey.

CORK

9068 "ESSO SOUTHAMPTON" - As recommended except that the class has been continued subject to the repairs to the starboard forced draught fan motor being examined and the motor tested under working conditions on completion of repairs by the end of February, 1961.



© 2021

Lloyd's Register
Foundation