

d by Chief Ship Surveyor

Received from Chief Ship Surveyor

GB

S NAME "CAPTAYANNIS" REPORT Rot. No. 53482

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to sternframe (E.W. 2,60) being specially examined next drydocking.

SPECIAL SURVEY (C) becomes due 1,64.

The ROTTERDAM Surveyors report (3,62), this ship in dry dock and due to grounding bottom shell plating also D.B.structure found extensively damaged.

It is also reported that the ship is to be broken up and she has left Rotterdam to proceed to the breaking-up yard.

The case has been forwarded for the information of the Committee.

IT IS SUBMITTED ACTION be DEFERRED pending further information.

RM
4-4-62.



© 2020

Lloyd's Register
Foundation

003038-003045-0006