

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

20th January, 1960.

Dear Sirs,

Motorship "DRUPA"

(S)
L A report of a survey held while this ship was in drydock at Singapore from October to December has now been received from the Society's Surveyors.

Some Metalock repairs were carried out to the main engine Nos.3 and 7 cylinder covers, but it was recommended that these repairs should be re-examined by June, 1960, and the Committee have continued the class subject to this matter receiving attention by the time stated.

The screwshaft was drawn for examination and the Auxiliary Boiler Survey was held. A record of Drydocking 11.59 and the notations of Screwshaft Examined 10.59 and ABS 12.59 have now been assigned.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

Messrs. Shell Tankers Ltd.,
Ibex House,
Minories,
London E.C.3.



© 2020

Lloyd's Register
Foundation

003038-003045-0163