

Received from Chief Ship Surveyor

13 AUG 1959

SHIP'S NAME

"THAUMASTUS"

REPORT

Fal.

No. 13544

VC

Outstanding Conditions of Class: SUBJECT to sternframe solepiece
(E.W. & reinforced 9.58) being specially examined
next drydocking,

S.R.L. — Appendix. (As before ~~or None~~)

Signature of Present Survey: (~~Afloat~~ in dry dock)

Docking and repairs.

Recommendation:

SUBMITTED record of 'DS. 7.59' be assigned as
recommended, SUBJECT as above, and to fractured shell plate
in way of No.7 wing tank (s.s.) also weld connection
to bilge keel (p.s) being specially examined and dealt
with as found necessary by the next drydocking.

DS' 7.59 SUBJECT.

IN S.R.L. APPENDIX.

Keel plates Nos. 3, 4, 5 & 6
from forward slightly set up.

THIS SHIP IS AT PRESENT LAID UP.