

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

16th May, 1961.

Dear Sirs,

Classn. (H)

s.s. "GADINIA"

With reference to the classification of this ship in the Society's Register Book, it is noted from the Shipping Papers that the vessel has been laid up in the River Blackwater since the 20th January last.

I think it well to remind you, however, that the Main Boiler Survey became due at the end of November, 1960 and the Port Screwshaft Survey will become due in August next.

The hull class is at present continued subject to end shackle of chain cable (port side) being verified at the earliest opportunity, to bottom shell plates C.3 and D.3 (port side) (doubled) being examined and dealt with as necessary at the next drydocking and to indented sheerstrake plate No.2 and shell plates Nos. 1 and 2 in strake below (port side forward) being examined and dealt with as necessary by the Special Survey.


The class of the machinery is continued subject to the starboard propeller being repaired before the vessel is recommissioned.

Yours faithfully,

c.c. IPS.

Clerk to the
Classification Committee.

Messrs. Shell Tankers Ltd.,
Ibex House,
Minories,
LONDON, E.C.3.



Lloyd's Register
Foundation

003046-003055-0192