

COPY

# LLOYD'S REGISTER OF SHIPPING



Port SINGAPORE

Date 1st October, 1959

This is to Certify that I have surveyed the motor tanker "DONACILLA", 8113 tons gross of LONDON, she lay afloat at Singapore on 27th & 30th September, 1959 on account of fractured starboard hawsepipe, of which the date of occurrence was stated to be not known.

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all <sup>Temporary</sup> repairs recommended by me have been completed to my satisfaction, also that I will recommend that she be continued as classed without fresh record of S.S. subject to the starboard hawsepipe being renewed at the next Special Survey, and as previously recommended, to shell plates C.14 D.14 & D.12 from aft (ps) and H.3 (p & s) being specially examined and dealt with as necessary at the next Special Survey.

being fit to carry

*J. MacLeod*

Surveyor to Lloyd's Register.

( J. MACLEOD )

### KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BIS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	SS(P)	Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Part. B) 60m,3,58 (MADE AND PRINTED IN ENGLAND.)

003046-003055-0330