

Chief Surveyors.....

Received from Chief Surveyors.....

NAME "HORNO" REPORT Flt. No. 147681.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

of Survey Temporary damage repairs. When due .....

N O T E D

SUBJECT to set up shell plating and buckled floors, etc. in way of No.2 D.B. tank(p.s.) and set in shell plating in 'E', 'F' & 'G' strakes, etc.(p.s.f.), being permanently repaired, and to stem and forecastle plating (p.s.) being dealt with at the Special Survey.

*AM*  
8.10.51



© 2020

Lloyd's Register  
Foundation

003056-003064-0136