

S.S. "MAURITZ"

Report Hbg

No. 913.

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in  $\frac{1}{100}$  of an inch.

[illegible]

Drillings ~~at ends to be made~~ in the vicinity of the ~~peak~~ bulkheads.  
in holds ER

003058-003064-0141