

Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....
 Lon. 117447
 Bel. 14667
 Gls. No. 73527

SHIP NAME "BRITISH MARINER" REPORT

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Type of Engine Oil Engine 4 SCSA.

6 cylinders 29 1/8" - 59 1/16"

MN 696

If Boilers fitted with forced draught -

Tail Shaft. If fitted with a continuous liner Yes

If fitted with an outside gland of approved type No.

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letter of the 28.3.47 for a service speed of 115 R.P.M.

This vessel's machinery appears to have been built in accordance

with the Rules and the approved plans, and it is submitted she is

eligible to be classed LMC 12,48

2 DB 150 lb.

End



© 2021
20.1.49.

Lloyd's Register
Foundation

003065-003074-0190