

CABLES: "PORTRUST, RANGOON"

TELEPHONE: { OFFICE S. 900 EX. 57.
RES. N. 191.

J. H. KIRKHAM,
P. BOX 1, RANGOON.

24th March 1958.

The Director,
Heilgers (Burma) Ltd.,
Chartered Bank Building,
Rangoon.


X PPR

Dear Sir,

S.S. "NOEMI"

Reference your LNR/65/598 dated 11th March 1958, requesting a survey on the above vessel, I have to report that the undersigned proceeded on board the vessel a.m. 12th March 1958 and contacted the Master, Capt. Roll, who stated that the cargo damaged was in his opinion not the result of structural defect of the vessel and therefore did not consider a Classification Survey necessary. Accordingly the survey was not proceeded with.

Yours faithfully,



c.c. Secretary, Lloyd's Register of SURVEYOR TO LLOYD'S REGISTER
Shipping - Undernoted text of letter referred
to above.

"The above vessel arrived with a cargo of cement in bags from Constanza and commenced discharge at 0930 hours on the 28th March 1958 at No.2 Sule Pagoda Wharf.

At the bottom of No.3 Hold it was found that a number of bags were stained and the cement hardened making it necessary to ease the bags with a pickaxe. We have requested Lloyds cargo Surveyor to survey the cargo to ascertain if possible the cause of the damage and we would request you to survey the hold (No.111) and forward to us 4 copies of your report.

Discharge from this hold has been completed and the hold is now ready for inspection."



© 2020

Lloyd's Register
Foundation

003083-003091-0206

© 2020
Lloyd's Register
Foundation