

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

17th July, 1962.

GK/LMD^C

Dear Sirs,

Steamer "DIANA" (3339 tons)

Before your report No.7446 receives consideration you should state whether the auxiliary steam pipes above 3" bore (if fitted) were examined and found satisfactory.

As the Steam Pipe Survey is incomplete in regard to the saturated steam pipes for the cylindrical boiler smoke boxes you should issue an amended Interim Certificate and forward a copy to this office.

You should state why chain cable of 1 13/16" diameter was supplied instead of 1 7/8" as originally supplied.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

The Surveyors,
NAPLES.



© 2020

Lloyd's Register
Foundation

003692-003099-0213