

Received from Chief Ship Surveyor.....

11 SEP 1962

SHIP'S NAME

"DIANA"

REPORT

Nap.

No. 7446

GB

Outstanding Conditions of Class:

SUBJECT to 45 fathoms of chain cable being supplied at the earliest opportunity and to set over stem and stem plating being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix. (As before ~~or None~~)

Nature of Present Survey: (Afloat and ~~in dry dock~~)

Equipment - supply of 45 fathoms of chain cable as above.

Recommendation:

SUBJECT to set over stem and stem plating being specially examined and dealt with as necessary next drydocking, but without other condition.

As Now. Subject
Without.

IN S.R.L. APPENDIX.

Keel and garboard strake seams slightly wavy.

IT IS FURTHER SUBMITTED the Surveyors be requested to advise why chain cable of 1.13/16" dia. was supplied instead of 1.7/8" as originally supplied.

11/7/62
Subletter
dated 30/6/62
R.S.S.
11/7/62