

o's name "BEN AIN"

Port LIV.

No. 161095

1st Last survey date 23.2.63.

ss is subject to

NIL.

at this survey the boiler was examined under steam after the fitting of three tube stoppers to leaky stay tubes leaking slightly from local corrosion.

Whilst the stay tubes now stoppered were found to be tight and efficient meantime the Surveyor recommends the stay tubes being examined and satisfactorily dealt with at the next MBS. due 8.63.

It is submitted that this vessel is eligible to remain as **CLASSED.**

Subject as now recommended,

APD.
25.3.63.



© 2020

Lloyd's Register
Foundation

003106-003115-0136