

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

45825

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name "A M I G O" (ex. "Sundale")

Official No. _____

Port of Registry Monrovia

This ship has been under survey at Rotterdam


on 19th July, 1958 and the following alterations to the conditions of assignment of loadlines have now been effected/found:—

For the timber deck cargo freeboard it has been found that there are:

1) Eyeplates for lashings, riveted to sheerstrake not more than 10' apart or 6'6" from bridge, poop and forecastle bulkheads. ✓

2) 6" x .40" flat bar sockets for 9" square uprights, welded to stringer plate not more than 10' apart, with portable sockets 2½" x .40" over, connected to bulwark rail bar with bolts. ✓

Further the auxiliary steering gear has been found in good order. ✓

Noted
OK
13.8.58

© 2020

Lloyd's Register
Foundation

A copy of this Report has been placed on board.