

"AXEL JOHNSON"

- Got. Rpt.No.24059.

Before this case receives consideration
IT IS SUBMITTED the Surveyors be referred to their
Report No.18859 of 2,52 and be requested to
state what repairs were effected to the sternframe ^{They} above
reported to be bent as there is no indication of
repairs being effected in the present Report.

They should also be requested to
furnish the test certificates of the rudder head and
shaft as same are not attached to the report as stated. ³⁰¹⁵

S.P.K.
5-5-58.



© 2020

Lloyd's Register
Foundation

003162-003174-0221