

003181-003196-0087

1

Sent to Chief Surveyors _____


Received from Chief Surveyors _____

VESSEL'S NAME Stl Sc "BENEDICT" Report Low No. 9682**For the CHIEF SHIP SURVEYOR and CHIEF ENGINE SURVEYOR.**

(In cases which have to be submitted to the Cladding Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Cladding Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 1957.)

Nature of Survey 1st Entry When due Revised Rules

✠ 100 A.1. (Steel) "With Freeboard"

10" (Stl). Shelter D^k (Stl) 3rd D^k (Stl) except in No 5 & 6 holds
Cell D.B. 350' 999t, D.T.a 32' 730t, F.P.T. 93t, A.P.T. 36t.F.K, 8 B.H. (Coll B.H. to Shelter D^k, 7 B.H. to 2nd D^k) Cen, Claydo ACP
F 32'.

27.3.30

26.3.30

It is concluded the vessel has two rows of pillars as approved and that the tests for the flexible steel wire are as required by the Rules but the surveyor should be requested to state if this is so.