

10 AUG 1960

Received from Chief Ship Surveyor

SHIP'S NAME

"UMRAN"

REPORT

IST

No. 4931

standing Conditions of Class: SUBJECT to set in shell plates (p & s.f) being specially examined and dealt with as necessary at the next drydocking, and to indent No.1 keel plate from fwd. being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix. (As before ~~of 1959~~)

Condition of Present Survey: (Afloat ~~and in dry dock~~)

Examination afloat after grounding.

Recommendation:

SUBJECT as above but ACTION be DEFERRED for examination in dry dock after grounding.

Subject.

IN S.R.L. APPENDIX.

Indents in shell plating (p & s).

*Insert in SRh
D.Docking (grounding)*



© 2020

Lloyd's Register
Foundation