



Eng Reports

LLOYD'S REGISTER OF SHIPPING

20, Sathorn Road, Bangkok

30th July, 1962.

Telephone: 31704 & 31717

TT, B.Sc.I
BYOR

The Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street,
London, E2 C. 3.

Ref. Classn (S)


Dear Sir,

2725 - M.V. " BANDON "

The Port Tailshaft broke at sea and fell off with the Propeller, the broken section was very rust from sea water and opinion of why it broke could not be ascertained.

The Vessel docked for changing the Shaft only there being no time for Hull inspection, she will dock about October of Annual Survey as usual.

Yours faithfully,



D.C. Knott.

003191-003190-0130

ER

REPORTS

A more detailed description of the fracture would be appreciated, e.g. the position along the shaft, appearance etc together with information concerning the replace shaft & propeller.

Eng Reports

226 R

The Bangkok Surveyor should be asked for the required information.

7/8/62



© 2020

Lloyd's Register
Foundation