

23rd July, 1962.

NGKOK

25 "BANDON" - As recommended.

I shall be glad to learn the cause of the damage to the  
tailshaft, or give your opinion as to the cause of the  
failure of the shaft.

Please state whether an opportunity was taken to examine the  
p with a view to assigning a record of docking, and if so, you  
uld forward a Rpt.8 with your recommendations.



© 2020

Lloyd's Register  
Foundation

003181-003196-0131