

COPY

# LLOYD'S REGISTER OF SHIPPING



Port

Bangkok.

11th May, 1962.

This is to Certify that I have  
surveyed the Machinery of the N.V. "BANDON",  
of Bangkok,

that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also I will Recommend that in the case of this Vessel the following entries be made in the Supplement to the Register Book in the parts seen with date, CS.

that her Machinery Classification Record be continued in the Book.

now examined:

(S. Items only)

Port Tailshaft broken, propeller lost.  
 Spare Tailshaft, unused, fitted - Marks - H D 75, LLOYD'S,  
 No. 01-F 396, 23-7-51.  
 clearance - 1/32" after fitting.  
 Spare Propeller, used before. fitted - Marks undecipherable.  
 Gear down on Starboard Tailshaft - 3/32".

D.C. Knott, Engineer Surveyor to Lloyd's Register


### KEY TO ABBREVIATIONS

|     |  |        |                                   |
|-----|--|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey                    | SGS    | Steam Generator Survey            |
| CS  | Continuous Survey of Engines               | SPS    | Steampipe Survey                  |
| DBS | Donkey Boiler Survey                       | TS     | Tailshaft Survey                  |
| ES  | Engine Special Survey                      | TS(CL) | Tailshaft Survey—Continuous Liner |
| MBS | Main Boiler Survey                         | TSN    | Tailshaft renewed                 |
| MES | Modified Survey of Oil Engines             | TS(OG) | Tailshaft Survey—Oil Gland        |
| OF  | Fitted for oil fuel (date) FP above 150°F. |        |                                   |

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,5.60 (MADE AND PRINTED IN ENGLAND)



003181-003190-0135