

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 12th June 43. When handed in at Local Office 15th June 43. Port of NEWCASTLE-ON-TYNE

No. in Reg. Book Survey held at North Shields Date, First Survey + Last Survey 1st June 1943.

86400 on the Wood, Iron or Steel "EMPIRE CHEER" (No. of Visits)

TONNAGE:— Built at Lunderland. By whom Wm Crawford & Sons, Ld. When 1943.
GROSS 7297 Owners Ministry of War Transport Owners' Address
UNDER DK. 6818 Managers Lieut. W. R. Smith & Sons, Ld. Port belonging to Lunderland.
NET 4936.

Surveyed Afloat or in Dry Dock? Drydock Name of Dock Smith's Dock Co. Ld. Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements)

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR DOCKING.
how done - vessel placed in drydock, bottom & rudder cleaned examined & coated.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								


PRESENT CONDITION OF THE	
Decks	State if Tanks have been examined inside
Caulking of Decks	State if Tanks now tested
Coamings	Bulkheads
Beams & Fastenings	Ceiling
Outside Plating	Cement or Asphalt (State which.)
" " in way of sidelights	Rudder
Breasthooks	Steering gear and its connections
Transoms	Windlass
Frames	Have pumps now been examined and found efficient?
Reverse Frames	Have Sluice Valves now been examined and found efficient?
Longitudinals	Have Watertight Doors now been examined and found efficient?
Transverses	Have Ventilators and their Coamings been examined and found efficient?
Floors	
Keelsons	
Stringers	
Inner Bottom Plating	
Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Dbing. Plates under Sounding Pipes	When put on, Month Year
Engine Room Skylights	Boats
Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Oil Bunkers	Condition, how ascertained (State if wedges removed)
Scuppers	Sails
Cargo Hatchways	Equipment letter
Hatches	Anchors, No. of
Planking of Wood Vessels	Chain Locker
Caulking ditto	Cables (State if now ranged)
Treenails ditto	" length mean diamr. (on board)
Breasthooks & Stimson ditto	" Rule length size
Transoms Pointers, & Crutches ditto	Hawser & Warps
Timbers of Frame at openings ditto	Standing and Running Rigging
Ditto Ditto at other places ditto	
Stringers, Clamps & Shells ditto	
Sarking ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24."
Forwarded for the information of the Committee.

Survey Fee (per section 29)	£	Fees applied for,	19
Special Damage or Repair Fee (if any) (per sec. 29)	£	Received by me,	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

LICENCE CASE - NO FEE
Committee's Minute
Character Assigned
See f.e. rpt. Std. 33747 5

G. Campbell
Surveyor to Lloyd's Register of Shipping.



003181-003190-0264

If so, is the Report sent now, or when will it be sent?

The Surveyor is requested to write on or behind the space for Committee's Minute.

Is Certificate required? If so, to be sent to