

18 JUL 1960

Received from Chief Ship Surveyor

SHIP'S NAME "ORION" REPORT Skm. No. 12644

GB

Outstanding Conditions of Class: SUBJECT to rudder and mainpiece being removed together with quadrant and spare steering gear and dealt with as necessary next drydocking by 4,60 - ship not to navigate in ice meantime.

S.R.L. Appendix. ~~(as before or None)~~

Nature of Present Survey: (Afloat and in dry dock)

Docking: Damage repairs including subject item.

Recommendation:

SUBMITTED record of 'DS 4,60' be assigned, but without special condition.

DS 4,60 Without.

INSERT IN S.R.L. APPENDIX.
(Rudder stock twisted 25° (2,60))

IT IS FURTHER SUBMITTED the Surveyors be requested to state the twist in the rudder stock as this should have been stated for record purposes.