

17 JUN 1961

Received from Chief Ship Surveyor.....

SHIP'S NAME "THE EARL" REPORT Nwc. No. 117060

Standing Conditions of Class: SUBJECT to a bower anchor and one length of chain cable being supplied at the earliest opportunity.

L. Appendix. (~~As before~~ or None)

Surveys due: SPECIAL SURVEY (D) due 4,60. Postponement until 4,61 approved 4.4.60 provided a satisfactory G.E. is held.

Location of Present Survey: (~~At float and~~ in dry dock)

Docking: General Examination: Wear and tear repairs: Damage (1) ranging (2) grounding involving side shell plating forward and bottom shell plating in way of Nos. 1 & 2 D.B.tanks:

Special Features: Equipment - recovery of bower anchor and 15 fms. c.c. (subject item).

Interim Certificate in order (Yes-~~No-None~~)

Items Outstanding: (If any for S.S.)

ALL ITEMS.

Work to be completed by: See Committee Minute.

Recommendation:

Handwritten initials and date: JS 26-60

SUBMITTED record of 'DS 4,60' be assigned, subject to side shell plating in way of F.P.tank (s.s.) and Nos.1 & 2 holds (p & s) also bottom shell plating in way of Nos.1& 2 D.B.tanks (p & s) being specially examined and dealt with as necessary by the Special Survey, but without other condition.

DS 4,60 Subject Without.

IT IS FURTHER SUBMITTED postponement of the Special Survey until 4,61 merits approval.

