



# LLOYD'S REGISTER OF SHIPPING

Pearl Assurance House,

Royal Parade, Plymouth

Telegrams: Register, Plymouth

Telephone No. 67006

23rd February, 1962.

RECEIVED

24 FEB 1962

Dear Sir, Ans'd.....

"DISCOVERY II"  
Ply. Rpt.No. 8894.

With reference to your letter of the 25th ultimo, I have to confirm that I was in error in reporting that this vessel had 240 fathoms of anchor chain cable.

I have contacted the vessel and it has been confirmed that the amount of chain cable now on board is 275 fathoms, made up as follows:-

Part anchor - 10 x 12 $\frac{1}{2}$  fms.

Starbd.anchor- 12 x 12 $\frac{1}{2}$  fms.

Yours faithfully,

Surveyor to Lloyd's Register.

The Secretary,  
London.

003223-063232-0189

© 2020

Lloyd's Register  
Foundation

SR.  
REPORTS

MY

Noted  
R.T.C  
27/2/62



© 2020

Lloyd's Register  
Foundation