

25th January, 1962.

PLYMOUTH.

8894 "DISCOVERY II" - As recommended, postponement of the Special Survey until 3.63 having been approved.

The equipment originally supplied to this ship was 280 fathoms of 1.11/16" diameter chain cable, and at the last Special Survey held at Plymouth (Plymouth Report 8957 dated 4.3.58 refers) 330 fathoms were reported. It is concluded that you are in error in reporting the length of chain cable on board as 240 fathoms, but your confirmation is desired.



© 2020

Lloyd's Register
Foundation

003223-003232-0192