

WRECK
SECTION
SHIPPING

16th July, 1963.

Dear Sir

With reference to the Survey

now being held on the

I beg to inform you that, in consequence of the condition of this vessel's main engine lub oil pump body (Metalock repair) it will be my duty to recommend to the Committee that the same be re-examined before the end of September, 1965, as provided for in the Rules, an extract from which appears on the other side:—the continuance of the vessel's character in the Society's Register Book to be subject to the due fulfilment of this condition.

Yours faithfully,

Engineer Surveyor to Lloyd's Register

J. C. BENTLEY

0 The Superintendent Engineer,
BP Tanker Co. Ltd.,
Britannic House,
Finsbury Circus, E.C.2.

3,58

003233-003239-0116