


Clarity

This case is now in order except that the electrical spare gear requires to be placed on board as prescribed and the makers test certificates furnished for the two dynamos & the steering motor.

note to
NWb
6/6/40



© 2020

L.R. 4/4/40.

Lloyd's Register
Foundation

003240-005244-0011