

COPY

LLOYD'S REGISTER OF SHIPPING



Port LONDON

16th July 1962.

This is to Certify that I have

Surveyed the Machinery of the S.S. "CALABAN" 8305 tons gross of Liverpool as she lay afloat and in drydock at this port for Continuous Survey, Completion of Steam Pipe Survey, and Completion of the Main Boiler Survey

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book CS 7.62 (as previously recommended) now, CS 7.62 now and CS (with date) when the survey has been completed.

and that her Machinery Classification Record be continued in the Book. subject to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:

(C.S. Items only)

- Starboard main engine HP & MP valves and gears.
- Starboard main engine Nos:1,2 & 3 main bearings, and crank journals.
- Starboard main engine manoeuvring valve.
- Auxiliary condenser.
- Emergency fire and bilge pump.
- Steering machinery.
- Windlass.
- Emergency diesel generator engine.
- Sea connections and discharges on the starboard side.
- Port & Starboard main engines seen working & manoeuvring.

B.W. Oxford *for*

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
 CS Continuous Survey of Engines
 DBS Donkey Boiler Survey
 ES Engine Special Survey
 MBS Main Boiler Survey
 MES Modified Survey of Oil Engines
 OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
 SPS Steampipe Survey
 TS Tailshaft Survey
 TS(CL) Tailshaft Survey—Continuous Liner
 TSN Tailshaft renewed
 TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that: "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,5,60 (MADE AND PRINTED IN ENGLAND)

© 2020 Lloyd's Register Foundation
003245-003251-0033