

S/S "CALABAR"

LOX 147742

Before this case receives consideration, the Surveyor should be asked to clarify the following:-

- (1) Have all sea connections been examined, or only those on Starboard side? Rpt. + Cert. do not agree.
- (2) Which main engine driven pumps have been examined? Nothing on Certificate.
- (3) Have both main engines been seen working & manoeuvring? Nothing on Certificate.



© 2020

Lloyd's Register  
Foundation

*Ex*  
21/8/62

0400-152300-5412300